

### ***ELECTRICAL SERVICES***

- ✎ Electrical lines are placed at the most convenient location to source, usually in center rear of booth. Should special placement be necessary, a minimum of one hour electrical labor is required and an electrical layout must be provided. Electrical materials, including cables and/or extension cords, necessary to provide electrical service according to layout and/or special placement requests will be invoiced at prevailing rates. Labor and material charges apply to multiple lines with layout, all in-booth connections and lines run under carpet. Indicate on order form or separate layout if electrical is to be placed under carpet.
- ✎ Hardwire connections and terminations of 208 and 480 volt lines require a minimum of one hour electrical labor to connect and one hour electrical labor to disconnect. Estimated prepayment is due at time of order.
- ✎ **Electrical lines installed and not used are non-refundable. Standard rates apply to all lines ordered after the advance rate deadline.**
- ✎ Electrical orders must be specified in terms of amps, volts and watts. To determine electrical requirements, multiply the number of amps by volts per piece of equipment and add these numbers together for total wattage. For example, if total exceeds 2400 watts/120 volts, multiple 120 volt lines are required; 3500 watts requires one 2400 watt service and one 1200 watt service.
- ✎ All equipment must be properly tagged and wired with complete information: type of current, voltage, phase, cycle, horsepower, etc.
- ✎ All electrical equipment must be UL approved and comply with federal, state and local fire and safety codes. Electricians will refuse connections where exhibitor's wiring or equipment constitutes a safety hazard and/or code violation. Motors over ¾ horsepower must have a switch with overload and fuse protection. The I-X Center is not responsible for damage or inconvenience caused by voltage fluctuation or power failure.
- ✎ I-X Center electricians are authorized to cut floor coverings to gain access to utility floor ports, permitting installation of electrical services.
- ✎ Power is turned on one hour before show and turned off one hour after show.
- ✎ Twenty-four hour service is available and requires a minimum 20 amp/120 volt connection.
- ✎ All dedicated computer lines require a minimum 20 amp/120 volt connection.
- ✎ **Should any of the following apply, electrical labor is required:**
  - ✎ Power levels over 20 amp/120 volt
  - ✎ Electrical distribution under carpet
  - ✎ Electrical equipment wiring or repairs
  - ✎ Distribution from outlets to equipment
  - ✎ Booth to booth cable runs
  - ✎ Co-axial cables run within booth
  - ✎ Single and multiple electrical lines with layout or upon request of special placement
  - ✎ Connections of electrical motors to controls, including wiring of machinery

**ELECTRICAL SERVICES CONTINUED...**

DESCRIPTION	U / M	ADVANCE RATE	STANDARD RATE
<b>Electrical Service 120 Volt – Taxable</b>			
10 amp / 120 volt / 1200 watt / 1 phase	EA	<b>Order through Show Mgt.</b>	
20 amp / 120 volt / 2400 watt / 1 phase	EA	<b>Order through Show Mgt.</b>	
<b>Electrical Service 208 Volt – Single Phase – Taxable</b>			
30 amp / 208 volt / 7200 watt / 1 phase	EA	<b>\$371.30</b>	<b>\$482.70</b>
60 amp / 208 volt / 14400 watt / 1 phase	EA	<b>486.30</b>	<b>632.20</b>
100 amp / 208 volt / 24000 watt / 1 phase	EA	<b>850.90</b>	<b>1,106.20</b>
<b>Electrical Service 208 Volt – Three Phase – Taxable</b>			
30 amp / 208 volt / 10800 watt / 3 phase	EA	<b>481.30</b>	<b>625.70</b>
60 amp / 208 volt / 21600 watt / 3 phase	EA	<b>665.00</b>	<b>864.50</b>
100 amp / 208 volt / 36000 watt / 3 phase	EA	<b>1,057.60</b>	<b>1,374.90</b>
All 208 lines require a minimum of one hour electrical labor to connect and one hour electrical labor to disconnect.			
<b>Electrical Accessories and Special Services – Taxable</b>			
3 Plug Device	EA	<b>27.60</b>	<b>35.90</b>
6 Plug Power Strip	EA	<b>43.30</b>	<b>56.30</b>
25' Extension Cord	EA	<b>43.30</b>	<b>56.30</b>
50' Extension Cord	EA	<b>55.40</b>	<b>72.00</b>
24 Hour Electrical Service*	EA (per line)	<b>86.00</b>	<b>111.80</b>
<b>*24 Hour service requires a minimum 20 amp/120 volt electrical line.</b>			
Early Power Usage (prior to show)	EA (per line)	<b>86.00</b>	<b>111.80</b>
Priority Electrical Service (rush)	EA (per line)	<b>86.00</b>	<b>111.80</b>
Continuation of Electric (after close of show)	EA (per line)	<b>86.00</b>	<b>111.80</b>

**ELECTRICAL LABOR**

- ✎ † Labor is charged in hourly increments per worker. One hour per worker will be charged for labor ordered and not used. Labor cancelled without a 24 hour notice will be charged a one hour cancellation fee per worker.
- ✎ † Advance electrical labor necessary to scale electrical to print, layout on floor and/or install lines under carpet prior to exhibitor's arrival will be charged at prevailing hourly electrical labor rates. The I-X Center will proceed on straight time whenever possible.
- ✎ † All 208 and 480 volt lines require electrical labor. A minimum estimated prepayment of one hour labor at prevailing rates will be charged to connect and one hour to disconnect.
- ✎ † Final billing for labor is based on actual time and materials used. A prepayment based upon estimated usage is due at the time services are ordered.

DESCRIPTION	U / M	STRAIGHT TIME	OVERTIME	DOUBLE TIME
<i>Straight time: Weekdays 8:00 a.m. – 4:30 p.m. • Overtime: Weekdays 4:30 p.m. - midnight, Saturdays 8:00 a.m. – 4:30 p.m. Double time: Weekdays midnight – 8:00 a.m., Saturdays after 4:30 p.m., Sundays and Holidays</i>				
<b>Installation Electrical Labor – Taxable</b>				
Electrical Labor	HR	<b>\$99.75</b>	<b>\$149.60</b>	<b>\$199.50</b>
<b>Disconnect Electrical Labor – Taxable</b>				
Electrical Labor	HR	<b>99.75</b>	<b>149.60</b>	<b>199.50</b>